


## Attention Kartridg Pak Chub Machine Users



### **WE CAN SAVE YOU MONEY!!!!!!!**

We have a rebuild program for the heat seal assembly. If your chub machine uses an electrical resistance hot air seal unit similar to the one shown we will rebuild damaged or burned out units for \$ 270.00. (Price is based on receiving the entire used or damaged core.)

We have been repairing these components for over five years and had none returned. Our fix consists of cleaning the entire unit, unplugging nozzle if required, replacing insulator bushing if required, and replacing resistance coil piping. Kartridg Pak Chub Machine Users.

**Our part number for this rebuild is: AS-2920.....\$ 283.50**